

Boeing Commercial Airplanes
PAINT HANGAR WASTEWATER

SAMPLE# L22532-2
SITE# A42292
DATE 25-OCT-01
SAMPLE CODE Composite
DISCHARGE RATE 22620
TIME SPAN 3.5
TIME UNIT h
SAMPLE START TIME 1030

PARAMETERS	VALQUAL	CONCENTRATION (mg/l)	LOAD (lbs/day)	STATUS
Arsenic, Total, ICP	<MDL	ND	NA	OK
Cadmium, Total, ICP	<MDL	ND	NA	OK
Chromium, Total, ICP	-	.0564	0.0106	OK
Copper, Total, ICP	<MDL	ND	NA	OK
Lead, Total, ICP	<MDL	ND	NA	OK
Mercury, Total, CVAA	-	-	-	NA
Nickel, Total, ICP	<MDL	ND	NA	OK
Silver, Total, ICP	<MDL	ND	NA	OK
Zinc, Total, ICP	-	.0579	0.0109	OK
CYANIDE	-	-	-	NA
pH, Field	-	-	-	NA

Category: A433

H = Sample handling criteria compromised, R = data judged unusable,
NA = Not Applicable, ND = Not Detected, - = Not Sampled,
pH is in standard units, discharge rate = gallons/day.

King County reports three reporting digits for values above the Reporting Detection Limit (RDL) also referred to as the Practical Quantitation Limit (PQL) and two reporting digits for values between the RDL and the Method Detection Limit (MDL). Values below the MDL are reported here as not detected (ND). Reporting digits that are zero that fall at the end of the value after the decimal point are dropped which is a function of the database and not a reflection on the analytical precision.